










# PEBSSA - ALFA ROMEO

<p>60504302 <b>101 - 541</b> ⊗</p> <p>60504299 <b>101 - 141</b></p> <p>60504365 <b>101 - 241</b></p> 	<p><b>Alfasud</b> E, L, TI 77-83 Nuova Super 80-83 Sprint, Veloce 77-89</p> <p>1351 cc, 75 HP, 55 KW 1490 cc, 85 HP, 63 KW 1490 cc, 95 HP, 70 KW</p>
<p>60504302 <b>101 - 541</b> ⊗</p> <p>60504299 <b>101 - 141</b></p> <p>60504365 <b>101 - 241</b></p> 	<p><b>33</b> 1.3, 1.5 83-90</p> <p>1351 cc, 79 HP, 58 KW 1490 cc, 84 HP, 62 KW</p>
<p>60504302 <b>101 - 541</b> ⊗</p> <p>60504299 <b>101 - 141</b></p> <p>60538290 <b>101 - 270</b></p> 	<p><b>33</b> 1.5i Ti, 07/84-90</p> <p>1490 cc, 105 HP, 77 KW</p>
<p>60537816 <b>101 - 570</b> ⊗</p> <p>60537817 <b>CAT</b> <b>901.0000</b> without Lambda sonda χωρίς υποδοχή Λάμδα</p> <p>60580666 <b>CAT</b> <b>901.0001</b> with Lambda sonda με υποδοχή Λάμδα</p> <p>60538290 <b>101 - 270</b></p> <p>60546209 <b>(B) 101 - 272</b></p> 	<p><b>33</b> <span style="border: 1px solid black; padding: 2px;">CAT</span></p> <p>(A) 1.4 i.e., 04/90- 1351 cc, 87 HP, 64 KW (A) 1.5 i.e., 91- 1490 cc, 98 HP, 72 KW (A) 1.7 i, 04/90 1712 cc, 107 HP, 79 KW (B) 1.4 i.e Sportwagon, 91- 1351 cc, 88 HP, 65 KW (B) 1.5 i.e, 91- 1490 cc, 98 HP, 72 KW (B) 1.7 e 1712 cc, 105 HP, 77 KW</p>
<p>60564162 <b>CAT</b> <b>901.1000</b> without Lambda sonda χωρίς υποδοχή Λάμδα</p> <p>60528963 <b>101 - 062</b></p> <p>60530487 <b>101 - 262</b></p> 	<p><b>75</b> <span style="border: 1px solid black; padding: 2px;">CAT</span></p> <p>1.8i.e. 89-12/91 1779 cc, 120 HP, 88 KW 2.0 i, 89-12/91 1962 cc, 128 HP, 94 KW 2.0i TWIN SPARK 89-12/91 1962 cc, 145 HP, 107 KW</p>

# ALFA ROMEO - PEBSSA

<p><b>145</b>      <b>CAT</b></p> <p><b>1.3-1.4 - 1.6 - 1.7 16V BOXER</b> 1994-</p>	
<p><b>145</b>      <b>CAT</b></p> <p><b>1.4 - 1.6 - 1.8 - 2.0 16V TWIN SPARK</b> 1997-2001</p>	
<p><b>146</b>      <b>CAT</b></p> <p><b>1.3-1.4 - 1.6 - 1.7 16V BOXER</b> 1995-</p>	
<p><b>146</b>      <b>CAT</b></p> <p><b>1.4 - 1.6 - 1.8 - 2.0 16V TWIN SPARK</b> 1997-</p>	
<p><b>147</b>      <b>CAT</b></p> <p><b>1.6 16V TWIN SPARK</b> 2001/01-</p> <p>1598 cc 103 PS, 76 kW</p>	

# PEBSSA - ALFA ROMEO

<p>46823073 <b>CAT 901.3008</b> 5 ΒΙΔΕΣ / 5 BOLTS</p> <p>46809273 <b>CAT 901.3007</b> 4 ΒΙΔΕΣ / 4 BOLTS</p> <p>46739666 <b>CAT</b> <b>901.3005</b></p> <p>46739669 <b>101-098</b></p> <p>46739672 <b>101-298</b></p> 	<p><b>147 CAT</b></p> <p><b>1.6 16V</b> <b>TWIN SPARK</b> 2001/01-</p> <p>1598 cc 120 PS, 88 kW Mot.: AR32104</p>
<p>60574421</p> <p>60574420 <b>CAT</b> <b>901.2000</b></p> <p>60574432 <b>101 - 480</b></p> <p><b>101 - 080</b></p> <p><b>101 - 280</b></p> 	<p><b>155</b> <span style="border: 1px solid black; padding: 2px;">CAT</span></p> <p><b>1.7i Twin Spark</b> 10/92-</p> <p>1748 cc, 116 HP, 85 KW</p> <p><b>1.8i Twin Spark</b> 6/92-</p> <p>1773 cc, 126 HP, 93 KW</p> <p><b>2.0 i Spark</b> 1995 cc, 141 HP, 104 KW</p>
<p>0060652858 <b>101-599</b></p> <p>0060667304 <b>CAT</b> <b>901.2006</b></p> <p>0060652867 <b>101-799</b></p> <p>0060652524 <b>101-299</b></p> 	<p><b>156 CAT</b></p> <p><b>1.6-1.8-2.0 16V</b> <b>TWIN SPARK</b> 09/1997-04/2000</p>
<p>46823073 <b>CAT 901.3008</b> 5 ΒΙΔΕΣ / 5 BOLTS</p> <p>46809273 <b>CAT 901.3007</b> 4 ΒΙΔΕΣ / 4 BOLTS</p> <p>46739666 <b>CAT</b> <b>901.3005</b></p> <p>0060668123</p> <p>0060652524 <b>101-299</b></p> 	<p><b>156 CAT</b></p> <p><b>1.6-1.8-2.0 16V</b> <b>TWIN SPARK</b> 05/2000-</p>